UNITED STATES DEPARTMENT OF THE INTERIOR Office of Surface Mining Reclamation and Enforcement			Originating Office	US DOI, Off	fice of Surface Mining			
		ation and Enforcem	ent		Beckley, Wo	Park Drive est Virginia 25801		
	Number X24-111	1-440-003	TV <u>4</u>	Telephone Number	(304) 25	5-5265		
	Ten-Day Notice	to the State of	West Virginia				_	
	You are notified that, as a result of (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521 (a)(1) of the Act will be taken.							
	Permittee: SOU	TH FORK COAL (COMPANY, LLC		County:	GREENBRIER	Surface	
(Or Operator if No Permit) Mailing Address:	1295 ASHFORD I	HILL RD, , ASHFO	ORD, WV 25009			☑ Underground	
(M	Permit Number: ultiple Permits See Remarks)	U-3019-91	Mine Name: SO	UTH FORK DEEP	MINE		Other	
		LATION AND LOCA	ATION:					
	Permittee failed to include PEP(s) for the federally endangered species Candy Darter and its critical habitat for permits U-3019-91, O-3013-11, O-3012-11, O-3022-11, S-3012-19, S-3002-19, S-3005-11, S-3033-93, S-3010-16, S-3002-19, and S-138-78 Section of State Law, Regulation or Permit Reg 38-2-3.16.b Condition believed to have been violated:							
02	NATURE OF VIOL	LATION AND LOCA					_	
		comply with an Ord lays of issuance of th			ermittee to	submit permit revisio	ns that includes	
				te Law, Regulation or leved to have been vic		Reg 22-3-17.a		
03	NATURE OF VIOL	LATION AND LOCA	ATION:					
	Permittee failed to	seek a determinatio	n that mining is per	rmissible for permit	O-3022-11	L		
	Section of State Law, Regulation or Permit Reg 22-3-22(a), 22-3-22(d)(5), 38-2-3.21.c Condition believed to have been violated:							
	Remarks or Recom	mendations:						
	Date of Notice: 07/31/2024 Signature of Authorized Representative:							
Γ	Page 1 of 2	Signatur T	•		auto ID4	440		
	Page 1 of 2		Print Nar	me and ID: Mark Ca	arter ID#	44U	Revised July 8, 2024	

L	JNITED ST	ATES DE	PARTMENT OF 1	THE INTERIOR	Originating Office:	Beckley Area Office	
Office of Surface Mining					US DOI, Office of Surface Mining		
Reclamation and Enforcement			ent		313 Harper Park Drive		
TEN-DAY NOTICE			DAY NOTICE			Beckley, West Virginia 25801	
	Number	X24-111-	440-003	TV	Telephone Number:	(304) 255-5265	
	Ten-Day	Notice t	to the State of	West Virginia			
04	NATURE	OF VIOL	ATION AND LOCA	ATION:			
	Permittee	failed to r	eclaim permits S-3	005-11 and S-138-7	8 in accordance with	the approved Reclamation Pla	n.
				Section of Sta	te Law, Regulation or I	Permit Reg 38-2-14.15.a	
				Condition ben	leved to have been viola	ated.	
	NATURE	OF VIOL	ATION AND LOCA	ATION:			
					te Law, Regulation or I		
				Condition beli	leved to have been violation	ated:	
	NATURE	OF VIOL	ATION AND LOCA	ATION:			
	TWITCHE	01 (102)					
				Section of Sta	te Law, Regulation or I	Permit	
					leved to have been violation		
	NATURE	OF VIOL	ATION AND LOCA	ATION:			
					te Law, Regulation or I leved to have been viol		
	NATURE	OF VIOL	ATION AND LOCA	ATION:			
					te Law, Regulation or I		
	Condition believed to have been violated:						
	NATURE OF VIOLATION AND LOCATION:						
				Section of Sta	te Law, Regulation or I	Permit	
				Condition beli	leved to have been viola	ated:	
	Date of No	tice: 07	/31/2024				
				e of Authorized Rep	resentative:		
Г	Page 2	of 2	Ç	_	me and ID: Mark Car	etor ID# 440	
	ruge 2			riiit ivai	iic and ii). Wark Cal	161 ID# 11 0	
⊢							Revised July 8, 2024



U.S. DEPT. OF THE INTERIOR OFFICE OF SURFACE MINING




Citizen Complaint

Citizen Complaint Number CC24-111-002			Date Comple	aint Received	06/20/2024	
Complainant		WEST VIRGINIA HIGHLANDS (CONCERVANCY	Did c	itizen request confidentiality?
Nature of Complaint						
COMPLAINANT ALLEGES THAT THE REGULATING AUTHORITY HAS IMPROVIDENTLY ISSUED PERMI O-3022-11, PERMITTEE HAS FAILED TO COMPLY WITH REGULATING AUTHORITY ORDERS, FAILED TO INSTITUTE PROTECTION ENHANCEMENT PLANS, AND RECLAIM PERMITS.						
		ance Standard heck all that a		Ackn	owledgement L	etter 07/03/2024
x A	. Administ	rative		FO Decis	sion Letter to Ci	tizen
В	s. Hydrolog	ic Balance		Citizen Inforn	nal Review Rec	uest
С	C. Topsoil 8	& Subsoil				
x D). Backfillin	g & Grading		In	formal Review	Date
		Spoil Disposal		Resul	t of Informal Re	view
	Coal Min			Citizan Notifia	d of Review Re	eulte
	G. Use of E	xpiosive		Chizen Notine	a of iteview ite	Suits
	I. Subsider Roads	ice Control Plan		Comments		
	. Signs & N	//arkers				
к	Ü	Prohibitions				
	. Revegation					
		ng Land Use				



U.S. DEPT. OF THE INTERIOR OFFICE OF SURFACE MINING





1. Permittee/Person		9. Permit Num	ber	10. Permit Type		
SOUTH FORK COAL COMPANY, LLC	U-3019-91		PP			
2. Address		11. Field Visit	Date 12. Purpose	e 13. SRA Present		
1295 ASHFORD HILL RD		7/2/2024	CCR	N IS. SKAT FIESEN		
		mm - dd - yyyy				
3. City	4. State	14. Permit Sta	tus 15. Site Stati	us 16. Facility Type		
ASHFORD	4. State	IN 14. Ferrint Sta	AP	BD 10. Pacifity Type		
		—				
	Phone Number 4) 836-5860	17. OSM Office 111	18. CCID # CC24-111			
7. Operator Name, if Different than P	ermittee	20. M.S.H.A. ID # 21. State Abbrev. 22. County/Burrough 46-08505 WV GREENBRIER				
8. Mine Name	_	23. AVS Perm	ittee Entity ID Num	nber 24. State Office		
SOUTH FORK DEEP MINE		251407		Fayetteville		
25. Hours 50.0 a. Permit Review	26. Signature Block		27. Reviewing	Official:		
	Signature:	_	Signature:			
	Mark Carter, ID#	4440	Id	ohn Flesher		
c. Travel Time	Inspector's Name:		Reviewer's Name:			
d. Report Writing						
	Date: 7/31/2024		Date: 7/3	31/2024		
	PP = Permanent Program NP = No F	Permit				
Purpose Type Codes - Item 12 OxxOversight	RFxReclamation Fees		CCRCitizen Complain CCCitizen Complain	nt Referral (non-site visit nt (initial site visit)		
AxxAssistance	FxxFederal Actions	OCM in a section of a section	CCFAssistance SM inspector at any time during the review of the mine site			
Permit Status - Item 14						
A Active: Coal mining activities occurring or pe	rmitted but not yet has left t	ned: All surface and underground coal mining activities have ceased and operator the site without completing reclamation as defined in 30 CFR 840:11(g). orfeiture: Bond forfeiture officially in process or completed and reclamation in s or not yet commenced. Reclaimed Forfeiture: Forfeited site where all bonds have been used to reclaim sit not reclaimed to Program standards.				
disturbed. IN Inactive (Permanent Program Permit): Phase						
Temporary Cessation of Operations. (Interim Coal mining completed and reclamation activ						
BR Bond Release: Reclamation completed and	State Regulatory AB3 Reclaims	ed Forfeiture: Forfeite	d site that has been reclair	med to Program standards.		
Authority(RA) has released all of the bond (P	hase III Release). NA Not Appl	licable: When site is u	npermitted.			
Site Status - Item 15 ND No Disturbance: No coal mining and reclama operations have been started.	ng activity on site, site d release. e RA has granted	Forfeiture Pending	atus of site not determined. g: The RA is pursuing actions to			
EX Coal Exploration: Coal exploration operations	nt to 30 CFR		, collect the performance bond(s), n of forfeited site is in progress.			
started and where coal mining operations hav begun.	Phase I bond release	FR Forfeited and Rec completed.	claimed: Forfeiture reclamation			
AP Active Coal Producing: Coal surface mining activities are occurring.	l area. For interim	FO Abandoned Site:	Abandoned site that is permitted b			
AN Active Non-Producing: Active non-producing		there is no bond. WC Wildcat: Coal min	ning and reclamation operations ha			
such as tipple or preparation plant. NM No Mining: The Permit Status is active, site is Temporary Cessation, no surface coal mining activity, and site not regraded.	for the entire permitted areas not in P3 Phase III Release: Reclam the RA has released all bor	nation completed and	or are taking place the required perm	e and the activity is not covered by its from the RA.		
Facility Type Codes - Item 16 DAncillary (Ha		xploration Permits		anced Construction Exemption		
ASurface ERefuse and/o BUnderground FLoading Faci	or Impoundment INo	otice of Intent to Explor exempt 16 and 2/3	e LRemining site pe	rmitted under 30 CFR 785.25		
CPreparation Plant GStockpiles						
	Small Business Regulatory Enforce Your Comments a		BREFA)			

The Small Business and Agriculture Regulatory Enforcement Ombudsman and 10 Regional Fairness Boards were established to receive comments from small businesses about Federal agency enforcement actions. The Ombudsman will annually evaluate the enforcement activities and rate each agency's responsiveness to small business. If you are a small business (a business with 500 or fewer employees including those of affiliates) and wish to comment on the enforcement or compliance activities of OSM, call 1-888-REG-FAIR (1-888-734-3247).

Page 1

U.S. DEPT. OF THE INTERIOR OFFICE OF SURFACE MINING

Mine Site Evaluation

Permit U-3019-91 Field Visit Date 7/2/2024 Permittee/ **State Program** SOUTH FORK COAL COMPANY, LLC Person Number Continuation Page

					8	
28. Performance Standard Categories						
Codes:1=Compliance, 2=Noncompliance, 3=No	t Planned, 4=Not St	arted, 5=Noncompl	iance Identified Elsewhere, 6=	Previously Cite	ed, 7=Permit Defect	
A. Administrative	D. Backfilling	& Grading		н	Subsidence Control Plan	
1. 2 Mining within Valid Permit		Exposed Openings		I. Roads		
2 Mining within Bonded Area	2. _2 (Contemporaneous	Reclamation	1.	Road Construction	
3. 2 Terms & Conditions of Permit		Approximate Original			_ Certification	
4. Liability Insurance		Highwall Eliminat			_ Drainage	
5 Ownership and Control		Steep Slopes (inclu		4	_ Surfacing and Maintenance	
6 Temporary Cessation	6 I	Handling of Acid a	and Toxic Materials	5	_ Reclamation	
7 AML Rec. Fees - Non-Respondent	7 S	Stabilization (rills	and gullies)	J. Signs &	& Markers	
8 AML Rec. Fees - Failure to Pay	E. Excess Spo	il Disposal		1	Signs	
B. Hydrologic Balance	11				Markers	
1 Drainage Control	21	Drainage Control			Distance Prohibitions	
2 Inspections & Certifications	3	Surface Stabilizati	on	М	Distance 1 Tombitions	
3. Siltation Structures	4	Inspections & Cer	tifications	L. Revege	tation	
4 Discharge Structures	F. Coal Mine	Waste		1	Vegetative Cover	
5 Diversions		waste les/Impoundmen	ts)	2.		
6 Effluent Limits 7. Ground Water Monitoring	,	Drainage Control	,		Postmining Land Use	
8. Surface Water Monitoring	2	Surface Stabilizat	ion		2 opening 2 and 0 op	
9 Drainage - Acid-Toxic Materials	3			N. Other		
10 Impoundments		Inspections & Cer		General		
11 Stream Buffer Zones	5	Impounding Struc	tures	Performance Category		
	G. Use of Ex	plosives				
C. Topsoil & Subsoil 1 Removal	1	Blaster Certificati	on			
2. Substitute Materials	2.	Distance Prohibiti	ons			
3 Storage and Protection	3	Blast Survey/Sche Warnings & Reco	edule			
4. Redistribution						
		Control of Advers	e Effects			
Performance Standard Categor	ies	E.	Excess Spoil Disposal		(816/817.71-74) 71(e)	
30 CFR Counterparts		1.	Placement		71(e) 71(f)	
A. Administrative	773 11	3.	Surface Stabilization		71(g)	
Mining within Bonded Area Terms & Conditions of Permit	773.11	F.			71(h) undments)816/817.81-84)	
4. Liability Insurance	800.60	1.	Drainage Control		83(a)	
Ownership and Control ————————————————————————————————————	778.13 1(a) & \$16/\$17.131	2. 3.	Surface Stabilization		83(b)	
 AML Rec. Fees Non-Respondent 	870.15(b)	4.	Inspections and Certification	S	83(d) 84	
8. AML Rec. Fees Failure to PayB. Hydrologic Balance	870.15(a) (816/817 41-57)	G. 5.	Impounding Structures		84 (816/817.61-68)	
1 Drainage Control	·45	1.	Blaster Certification		61(c)	
Inspections & Certifications Siltation Structures	46	2.	Distance Prohibitions		61(d) 62-64	
4. Discharge Structures 5. Diversions	47	4.	Wamings & Records		66 & 68	
Diversions Effluent Limits	42	5. U	Control of Adverse Effects		67 (\$17.121-122)	
7. Ground Water Monitoring		I.	Roads	п	(816/817.150-151)	
Surface Water Monitoring DrainageAcid - Toxic Materials	41(f)	1.	Road Construction		150(c)	
10. Impoundments 11. Stream Buffer Zones	49 57	2. 3.	Certification Drainage		151(a) 150(b)-151(d)	
C. Topsoil & Subsoil	(816/817.22)	4	Surfacing and Maintenance -		150(e)-151(d)	
Removal — Substitute Materials. —	22(a)	J.	Signs & Markers		150(f) 816/817.11)	
 Storage and Protection 	22(c)	1.	Signs		11(a)(b) &(c)	
4. Redistribution————————————————————————————————————	22(d)	K.	Distance Prohibitions		11(a),(b),(d),(e),&(f) (761.11)	
 Exposed Openings816/817.13, 14 	.15, & 823.11 & 21	L.	Revegetation		(816/817.111-116)	
Contemporaneous Reclamation ——— Approximate Original Contour ———	102(a)(1)	1.	Vegetative Cover		111 & 116	
4 Highwall Flimination	102(a)(2)	2. M.	Postmining Land Use		(816/817.133)	
Steep Slopes (includes downslope) Handling of Acid & Toxic Materials	107 102(c)		6		(======)	
7. Stabilization (rills and gullies)	95(b)					

U.S. DEPT. OF THE INTERIOR OFFICE OF SURFACE MINING **Mine Site Evaluation**

Permittee/ Person SOUTH FORK COAL COMPANY, LLC Permit Number U-3019-91 Fiel	d Visit Date 7/2/2024	State Program Continuation Page
A. Specific State Law/Regulations Violated: Reg 38-2-3.16.b		-Site Impacts
B. Description: Permittee failed to include PEP(s) for the federally endangered species Candy Darter and its critical habitat for permits U-3019-91, O-3013-11, O-3012-11, O-3022-11, S-3012-19, S-3002-19, S-3005-11, S-3033-93, S-3010-16, S-3002-19, and S-138-78	People Blasting	Land Water Structures
C. Performance Standard: A3 D. Abated (Y/N): N E. OSM Action: 2 F. OSM Action Number: X24-111-440-003 Viol#: 01 G. Optional: H. Any Off-Site Impacts (Y/N): N I. Latitude: 0380931 J. Longitude: 0802316 K. Elevation:	Stability Hydrology Encroachment Other	
A. Specific State Law/Regulations Violated: Reg 22-3-17.a		-Site Impacts
B. Description: Permittee failed to comply with an Order, issued by WVDEP, requiring the permittee to submit permit revisions that includes PEP(s) within 45 days of issuance of the Order for multiple permits C. Performance Standard: A3 D. Abated (Y/N): N E. OSM Action: 2 F. OSM Action Number: X24-111-440-003 Viol#: 02 G. Optional: H. Any Off-Site Impacts (Y/N): N I. Latitude: 0380931 J. Longitude: 0802316 K. Elevation:	People Blasting Stability Hydrology Encroachment Other	Land Water Structures
A. Specific State Law/Regulations Violated: Reg 22-3-22(a), 22-3-22(d)(5), 38-2-3.21.c	L. Off	-Site Impacts
B. Description: Permittee failed to seek a determination that mining is permissible for permit O-3022-11 C. Performance Standard: A1 D. Abated (Y/N): N E. OSM Action: 2 F. OSM Action Number: X24-111-440-003 Viol#: 03 G. Optional: H. Any Off-Site Impacts (Y/N): N I. Latitude: 0380931 J. Longitude: 0802316 K. Elevation:	People Blasting Stability Hydrology Encroachment Other	Land Water Structures
A. Specific State Law/Regulations Violated: Reg 38-2-14.15.a	L. Off	-Site Impacts
B. Description: Permittee failed to reclaim permits S-3005-11 and S-138-78 in accordance with the approved Reclamation Plan. C. Performance Standard: D2 D. Abated (Y/N): N E. OSM Action: 2 F. OSM Action Number: X24-111-440-003 Viol#: 04 G. Optional: H. Any Off-Site Impacts (Y/N): N I. Latitude: 0380931 J. Longitude: 0802316 K. Elevation:	People Blasting Stability Hydrology Encroachment Other	Land Water Structures

- DSM Action

 1) Deferred to State Action
 2) TDN Issued
 3) NOV Issued
 4) FTA-CO Issued
 5) IH-CO Issued
 6) ID-CO Issued (Imminent Danger to Public)
 7) Previously cited by RA, abatement pending
 8) Abated during or before OSM inspection
 9) Follow-up of Federal Action
 5) IH-CO Issued
 0) Off-site impact with no violation

Off-Site Impacts
For each type of impact and resource affected, enter
"N, D, or J" to describe the degree of off-site impact:
N - Minor Occurrence
D - Moderate Occurrence
J - Major Occurrence

Page 3 of 3

Revised October 1, 2010

MINE SITE EVALUATION NARRATIVE

Permit Number: U-3019-91, O-3022-11, S-3012-19, S-3005-11, S-3033-93, S-3010-16, S-3002-19, 0-3012-11,

O-3013-11, S-3033-93, and S-138-78 (Permits)

Permittee: South Fork Coal Company, LLC

Inspection Date: 6/24/2024

Inspection Type: CCR

Participants: Mark Carter OSMRE

This Citizen Complaint Referral was initiated by a complaint received by OSMRE from the West Virginia Highlands Conservancy (citizen) on June 20, 2024.

The citizen alleges that a Protection Enhancement Plan(s) (PEP) addressing the critical habitat of the listed species (Candy Darter) are not included in the Permits.

The citizen alleges the permittee failed to comply with an order of the Director issued by West Virginia Department of Environmental Protection (WVDEP) between 4/10/2024 and 4/30/2024 on inspection reports (MR-6's) that stated that the permittee had 45 days from the issuance of the order to submit an insignificant revision that included a PEP(s) for multiple permits.

The citizen alleges that permits U-3019-91, O-3022-11, and S-3012-19 encroach upon National Forest lands and have been improvidently permitted. Specifically, a section of Permit O-3022-11 crosses the U.S. National Forest lands, referred to as Tract M on the Permit's proposal and drainage map.

The citizen alleges that the permittee has failed to reclaim permits S-3005-11 and S-138-78.

Please see the attached Ten-Day Notice (TDN) that includes the following violations.

TDN Violation # 1: Permittee failed to include PEP(s) for the federally endangered species Candy Darter and its critical habitat for permits U-3019-91, O-3013-11, O-3012-11, O-3022-11, S-3012-19, S-3002-19, S-3005-11, S-3033-93, S-3010-16, S-3002-19, and S-138-78. *38-2-3.16.b* (see below for regulatory provisions violated)

TDN Violation # 2: Permittee failed to comply with an Order, issued by WVDEP, requiring the permittee to submit permit revisions that includes PEP(s) within 45 days of issuance of the Order for permits U-3019-91 (4/10/2024 MR-6), O-3013-11(4/22/2024 MR-6), O-3012-11 (4/22/2024 MR-6), O-3022-11 (4/10/2024 MR-6), S-3012-19 (4/10/2024 MR-6), S-3005-11 (4/22/2024 MR-6), and S-138-78 (4/30/2024 MR-6). 22-3-17.a (see below for regulatory provisions violated)

TDN Violation # 3: Permittee failed to seek a determination that mining is permissible for permit O-3022-11 where it crosses U.S. Forest Lands, referred to as Tract M on the Permit proposal and drainage map.. 22-3-22(a), 22-3-22(d)(5), 38-2-3.21.c (see below for regulatory provisions violated)

TDN Violation # 4: Permittee failed to reclaim permits S-3005-11 and S-138-78 in accordance with the approved Reclamation Plan. 38-2-14.15.a (see below for regulatory provisions violated)

MINE SITE EVALUATION NARRATIVE

38-2-3.16 Fish and Wildlife Resources Information

- **38-2-3.16.b.** Each application shall include a description of how, to the extent possible using the best technology currently available, the operator will minimize disturbances and adverse impacts on fish and wildlife 38CSR2 and related environmental values, including compliance with the Endangered Species Act, during the surface mining and reclamation operations and how enhancement of these resources will be achieved where practicable.
- §22-3-22. Designation of areas unsuitable for surface mining; petition for removal of designation; prohibition of surface mining on certain areas; exceptions; taxation of minerals underlying land designated unsuitable.
 - (a) The director shall establish a planning process to enable objective decisions based upon competent and scientifically sound data and information as to which, if any, land areas of this state are unsuitable for all or certain types of surface-mining operations pursuant to the standards set forth in subdivisions (1) and (2) of this subsection: Provided, that such designation shall not prevent prospecting pursuant to section seven of this article on any area so designated.
 - (d) After the third day of August, one thousand nine hundred seventy-seven, and subject to valid existing rights, no surface-mining operations, except those which existed on that date, shall be permitted.
 - (5) On any federal lands within the boundaries of any national forest: Provided, That surface coal mining operations may be permitted on the lands if the secretary of the interior finds that there are no significant recreational, timber, economic or other values which may be incompatible with the surface-mining operations: Provided, however, That the surface operations and impacts are incident to an underground coal mine.

38-2-3.21 Prohibitions and Limitations on Mining

- **38-2-3.21.c.** Where the proposed operation would include Federal lands within the boundaries of any national forest when the applicant seeks a determination that mining is permissible under paragraph (5), subsection (d), section 22 of the Act, the applicant shall submit a permit application to the field office of the Federal Office of Surface Mine Reclamation and Enforcement with a request that such determinations be made.
- **§22-3-17.** Notice of violation; procedure and actions; enforcement; permit revocation and bond forfeiture; civil and criminal penalties; appeals to the board; prosecution; injunctive relief.
 - (a) If any of the requirements of this article, rules promulgated pursuant thereto or permit conditions have not been complied with, the director shall cause a notice of violation to be served upon the operator or the operator's duly authorized agent. A copy of the notice shall be handed to the operator or the operator's duly authorized agent in person or served by certified mail addressed to the operator at the permanent address shown on the application for a permit. The notice shall specify in what respects the operator has failed to comply with this article, rules or permit conditions and shall specify a reasonable time for abatement of the violation not to exceed thirty days. If the operator has not abated the violation within the time specified in the notice, or any reasonable extension thereof, not to exceed sixty days, the director shall order the cessation of the operation or the portion thereof causing the violation, unless the operator affirmatively demonstrates that compliance is unattainable due to conditions totally beyond the control of the operator. If a violation is not abated within the time specified or any extension thereof, or any cessation order is issued, a mandatory civil penalty of not less than seven hundred fifty dollars per day per violation shall be assessed. A cessation order remains in effect until the director determines that the violation has been abated or until modified, vacated or terminated by the director or by a court. In any cessation order issued under this subsection, the director shall determine the steps necessary to abate the violation in the most expeditious manner possible and shall include the necessary measures in the order.

MINE SITE EVALUATION NARRATIVE

38-2-14.15. Contemporaneous Reclamation Standards.

14.15.a. General. This subsection establishes general performance standards relating to backfilling, regrading, and stabilization for all surface mining operations within the State. The mining and reclamation plan for each operation shall reflect these standards in describing how the mining operations and reclamation operations are to be coordinated to minimize total land disturbance and to keep reclamation operations as contemporaneous as possible with the advance of mining operations. Particular emphasis must be given to (1) limiting the size and number of excess spoil disposal fills; (2) locating and configuring excess spoil disposal fills in such a way so as to minimize land disturbance; (3) controlled handling and placement of all spoil material; and (4) the timing and sequence of backfilling and regrading operations which will minimize the ratio of disturbed and unreclaimed area versus undisturbed and reclaimed area. All surface mining operations shall be conducted in such a manner so as to comply with the approved reclamation plan and the standards set forth in this subsection.